# Error Message (0xc0000005)

When executing EasyBuilder Pro.exe, if an error message appears as below, please check if AVAST ANTIVIRUS software is installed on your PC.

AVAST ANTIVIRUS software of program version 5.1.889 or later has a possibility to conflict with EasyBuilder Pro software and cause failure in EasyBuilder Pro execution. To deal with this, please pause AVAST ANTIVIRUS software or remove it from your PC.